

Fig.2







Fig.3










Fig.7




Fig.8

114

DESCRIPTION	SETTING	
CONTROL IDENTIFICATION HIERARCHY NUMBER No	4	
CONTROL CATEGORY IDENTIFIER C-ID1	1	
CONTROL CATEGORY IDENTIFIER C-ID2	3	
CONTROL CATEGORY IDENTIFIER C-ID₃	2	
CONTROL CATEGORY IDENTIFIER C-ID4	0	

DEVICE ID	D-ID1	D-ID2	D-ID3	D-ID4
ID SETTING	1:PRINTER	1:ELECTROPHOTOGRAPHIC	1:CO. A	1:AAA
		2:SUBLIMATION	2:CO. B	2:BBB
		3:INK JET	3:CO. C	3:000
	2:MONITOR	1:CRT	1:CO. A	1:AAA
		2:TRANSMISSIVE LCD	2:CO. B	2:BBB
		3:REFLECTIVE LCD	3:CO. C	3:000
	3:PROJECTOR	1:LCD	1:CO. A	1:AAA
		2:DLP	2:CO. B	2:BBB

115

CONTROL PARAMETER SETTING		
	2. 2	
GAMMA CORRECTION VALUE		
TARGET COLOR SPACE	NTSC	
sRGB NEGATIVE VALUE TREATMENT	1 (VALID)	
SHADOW	5	
HIGHLIGHT	2	
CONTRAST	0	
BRIGHTNESS	4	
RGB COLOR BALANCE	R0/G-1/B2	
CHROMATICITY	0	
SHARPNESS	THRESHOLD VALUE 2, APPLIED LEVEL 3	
STORED COLOR CORRECTION	GREEN 0,0,0 (UNASSIGNED) SAPCE 0,0,0 (UNASSIGNED) SKIN 0,0,0 (UNASSIGNED) RED 0,0,0 (UNASSIGNED)	
AUTO ADJUST	5	
PAPER	3(PHOTOGRAPHIC PAPER)	
RESOLUTION	4(PHOTOGRAPH)	
PRINTING DIRECTION	1(ON)	




Fig.12






Fig.13



DESCRIPTION	SETTING
DEVICE IDENTIFICATION HIERARCHY NUMBER Nd	4
DEVICE CATEGORY IDENTIFIER D-ID1	1
DEVICE CATEGORY IDENTIFIER D-ID2	3
DEVICE CATEGORY IDENTIFIER D-ID3	2
DEVICE CATEGORY IDENTIFIER D-ID4	0



$$\begin{pmatrix} R \\ G \\ B \end{pmatrix} = \mathbf{S} \begin{pmatrix} Y \\ Cb - 128 \\ Cr - 128 \end{pmatrix}$$
$$\mathbf{S} = \begin{pmatrix} 1 & 0 & 1.40200 \\ 1 & -0.34414 & -0.71414 \\ 1 & 1.77200 & 0 \end{pmatrix}$$

Fig.17

$$\begin{pmatrix} X \\ Y \\ Z \end{pmatrix} = \mathbf{M} \begin{pmatrix} Rt' \\ Gt' \\ Bt' \end{pmatrix} \qquad \mathbf{M} = \begin{pmatrix} 0.6067 & 0.1736 & 0.2001 \\ 0.2988 & 0.5868 & 0.1144 \\ 0 & 0.0661 & 1.1150 \end{pmatrix}$$

 $Rt, Gt, Bt \geq 0$

$$Rt' = \left(\frac{Rt}{255}\right)^{r} \qquad Gt' = \left(\frac{Gt}{255}\right)^{r} \qquad Bt' = \left(\frac{Bt}{255}\right)^{r}$$

Rt, Gt, Bt < 0

$$Rt' = -\left(\frac{-Rt}{255}\right)^{r} \qquad Gt' = -\left(\frac{-Gt}{255}\right)^{r} \qquad Bt' = -\left(\frac{-Bt}{255}\right)^{r}$$

$$\begin{pmatrix} Rw \\ Gw \\ Bw \end{pmatrix} = N^{-1} \begin{pmatrix} X \\ Y \\ Z \end{pmatrix}$$

$$Rw' = \left(\frac{Rw}{255}\right)^{1/r} \qquad \qquad Gw' = \left(\frac{Gw}{255}\right)^{1/r} \qquad \qquad Bw' = \left(\frac{Bw}{255}\right)^{1/r}$$